### **ENVIRONMENTAL CHEMISTS**

## Analysis For Total Metals By EPA Method 200.8

Client ID: M122664 Date Received: 05/21/09 05/26/09 Date Extracted: Date Analyzed: 05/27/09 Matrix: Water Units: ug/L (ppb)

Client: Project: Lab ID: Data File: Instrument:

Alaskan Copper Works PO M122664, F&BI 905211

905211-01 x10 905211-01 x10.033 ICPMS1

Operator: btb

Upper

Internal Standard: Germanium

% Recovery: 103

Lower Limit: 60

Limit: 125

Concentration Analyte: ug/L (ppb)

Chromium 457 Nickel 508 Copper 791 Zinc 61.6

### **ENVIRONMENTAL CHEMISTS**

## Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank Client: Alaskan Copper Works Project: PO M122664, F&BI 905211 Date Received: Not Applicable 05/26/09 Lab ID: Date Extracted: 19-215 mb Date Analyzed: 05/27/09 Data File: I9-215 mb.031 Matrix: Water Instrument: ICPMS1 Units: ug/L (ppb) Operator: btb

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 122 60 125

<1

Analyte: Concentration ug/L (ppb)

Chromium <1
Nickel <1
Copper <1

Zinc

#### **ENVIRONMENTAL CHEMISTS**

Date of Report: 06/02/09 Date Received: 05/21/09

Project: Metro Self Monitor, PO M122664, F&BI 905211

## QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 905212-01 (Duplicate)

Analyte	Reporting Units	Sample Result	Duplicate Result	Relative Percent Difference	Acceptance Criteria		
Chromium	ug/L (ppb)	<1	<1	nm	0-20		
Nickel	ug/L (ppb)	<1	<1	nm	0-20		
Copper	ug/L (ppb)	15.4	15.6	1	0-20		
Zinc	ug/L (ppb)	12.3	11.6	6	0-20		

Laboratory Code: 905212-01 (Matrix Spike)

Analyte	Reporting Units	Spike Level	Sample Result	Percent Recovery MS	Acceptance Criteria
Chromium	ug/L (ppb)	20	<1	103	50-150
Nickel	ug/L (ppb)	20	<1	110	50-150
Copper	ug/L (ppb)	20	15.4	<b>104</b> b	50-150
Zinc	ug/L (ppb)	50	12.3	99 b	50-150

Laboratory Code: Laboratory Control Sample

Analyte	Reporting Units	Spike Level	Percent Recovery LCS	Acceptance Criteria
Chromium	ug/L (ppb)	20	99	70-130
Nickel	ug/L (ppb)	20	96	70-130
Copper	ug/L (ppb)	20	97	70-130
Zinc	ug/L (ppb)	50	97	70-130

#### **ENVIRONMENTAL CHEMISTS**

# **Data Qualifiers & Definitions**

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

#### **ENVIRONMENTAL CHEMISTS**

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

June 2, 2009



### **INVOICE # 09ACU0602-1**

Accounts Payable Alaskan Copper Works 628 South Hanford Seattle, WA 98134

RE: Project Metro Self Monitor, PO M122664, F&BI 905211 - Results of testing requested by Gerry Thompson for material submitted on May 21, 2009.

FEDERAL TAX ID #(b) (6)

end Report To Sake D Jho-050-	SAMPLERS (signature)	TURNAROUND TIME
company ALASKA Cyppon works  address 628 S. Hardred St	PROJECT NAMENO. PO#  metro Self rundon m/226	Standard (2 Weeks)  Rush Granges authorized by:
ty, State, ZIP Season WA 58/39 one #206-571-6033 Fax # 206-382-43	REMARKS	SAMPLE DISPOSAL  Dispose after 30 days Return samples Will call with instructions

Sample ID	Lab ID	Date	Time	Sample Type	# of containers	TPH-Diesel	TPH-Gasoline	BTEX by 8021B	VOCs by 8260	SVOCs by 8270	HFS	7 2 m 2 2	, , , , ,	, Ka			***	Notes
m 122664	Ol	Shi	12:30	420	/							I					7.1	
											-			_				
							-			$\dashv$	1							
					7/													
,																		
ia							_		_		_						MENOR WELL	31 
	_			12 11 11 11 11 11 11 11 11 11 11 11 11 1		Н	-		-	-	$\dashv$	$\dashv$						1; 
		/	(i)						7	1	+	-					12	an www.acare
Friedman & Bruya, Inc. 3012 16th Avenue West	Relinquisited by	SIGNATUI	RE	> Ge	PRINT	NAN	Æ	σ.		Ŧ		co		NY			DATE	TIME 3.03pm
Seattle, WA 98119-2029 Received by: Horns		hl	HON	HONE NAMEN					İ	TCM.					ľ	V V		
Ph. (206) 285-8282 Fax (206) 283-5044	Received by:				(a)											-		
FORMS\COC\COC.DOC		\T	ofe y			****				<b></b>		Sa	mpl	les re	ceiv	ed at	ತ್ತು	_°C

#### **ENVIRONMENTAL CHEMISTS**

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

June 2, 2009

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on May 21, 2009 from the Metro Self Monitor, PO M122664, F&BI 905211 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0602R.DOC